

# Supplemental Type Certificate

*Number* SA5137NM

*This certificate, issued to*

**Rosen Sunvisor Systems  
86365 College View Road  
Eugene, OR 97405**

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part \* of the \* Regulations.*

*Original Product—Type Certificate Number:* \*See attached FAA Approved Model List (AML)  
*Make:* No. SA5137NM for a list of approved airplane.  
*Model:* models and applicable airworthiness regulations

*Description of the Type Design Change:* Installation of sun visor in accordance with ROSEN Product Development, Inc. Drawing List No. RCS-300 / 400-00 DL, Revision B, dated February 14, 2005, or later FAA-approved revisions.

*Limitations and Conditions:* Approval of this change in type design applies to the above aircraft model only and should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Model List (AML) No. SA5137NM, dated February 22, 2005, or later FAA approved revision, must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* December 17, 1990

*Date reissued:* February 22, 2005

*Date of issuance:* May 2, 1991

*Date amended:* September 5, 2002; June 26, 2003;  
February 22, 2005

*By direction of the Administrator*



*Dore M Anderson*  
(Signature)

Acting Manager, Seattle Aircraft  
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

**FAA APPROVED MODEL LIST (AML) SA5137SE  
FOR  
INSTALLATION OF ROSEN SUNVISOR SYSTEMS COCKPIT SUN VISOR**

ISSUE DATE: May 2, 1991

ITEM	AIRPLANE MAKE	AIRPLANE MODEL	TYPE CERTIFICATE NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DRAWING LIST		AML AMENDED DATE
					NUMBER	REVISION NO. AND DATE	
1.	Cessna	T303	A34CE	14 CFR part 23	RCS-300/ 400-00 DL	B 02/14/05	2/22/05
2.	Cessna	310, 310A, 310B, 310C, 310D, 310E, 310F, 310G, 310H, E310H, 310I, 310J, 310J-1, E310J, 310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R	3A10	CAR 3	RCS-300/ 400-00 DL	B 02/14/05	2/22/05
3.	Cessna	320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F, 335, 340, 340A	3A25	CAR 3	RCS-300/ 400-00 DL	B 02/14/05	2/22/05
4.	Cessna	336	A2CE	CAR 3	RCS-300/ 400-00 DL	B 02/14/05	2/22/05
5.	Cessna	401, 401A, 401B, 402, 402A, 402B, 402C, 411, 411A, 414, 414A, 421, 421A, 421B, 421C, 425	A7CE	CAR 3	RCS-300/ 400-00 DL	B 02/14/05	2/22/05
6.	Cessna	404, 406	A25CE	14 CFR part 23	RCS-300/ 400-00 DL	B 02/14/05	2/22/05
7.	Cessna	441	A28CE	14 CFR part 23	RCS-300/ 400-00 DL	B 02/14/05	2/22/05

FAA APPROVED:

*Dorr M Anderson*  
Acting Manager, Seattle Aircraft  
Certification Office

REISSUED: February 22, 2005

AMENDED: September 22, 2003; March 22, 2003; February 22, 2005

**FAA APPROVED MODEL LIST (AML) SA5137SE  
FOR  
INSTALLATION OF ROSEN SUNVISOR SYSTEMS COCKPIT SUN VISOR**

**ISSUE DATE: May 2, 1991**

ITEM	AIRPLANE MAKE	AIRPLANE MODEL	TYPE CERTIFICATE NUMBER	CERTIFICATION BASIS FOR ALTERATION	FAA APPROVED DRAWING LIST		AML AMENDED DATE
					NUMBER	REVISION NO. AND DATE	



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

**Transport Airplane Directorate  
Aircraft Certification Service**

1601 Lind Avenue S.W.  
Renton, Washington 98055-4056

FEB 22 2005

In Reply  
Refer To: 150S-05-83

Mr. Gary Hanson  
Rosen Sunvisor Systems, LLC  
86365 College View Road  
Eugene, Oregon 97405

Dear Mr. Hanson:

This letter is provided in response to your letter, dated January 24, 2005, requesting an update to Supplemental Type Certificate (STC) SA5137NM. The reason for the update is to change the document format for the Drawing List (DL) RCS-300/400-00 DL Revision B, dated February 14, 2005, and to update the component, assembly and installation documents. Also, the Approved Model List (AML) for STC SA5137NM Item 7 was found to have a minor typographical error. The AML referenced the Model '401' in Item 7 instead of '411.' The STC and AML have since been revised to add the new DL and correct the model error and are enclosed with this letter.

Sincerely,

A handwritten signature in cursive script that reads "Dorr M. Anderson".

Dorr M. Anderson  
Manager, Cabin Safety and  
Environmental Systems Branch  
Seattle Aircraft Certification Office

Enclosure